

Purpose: As per CLI-ECA 064-S710 Schedule E Section 5.2 the Owner shall prepare an annual performance report for the authorized system. The report must be submitted to the Director (MECP) on or before April 30 of each year and covers the period from January 1st to December 31st of the preceding calendar year.

Stormwater System ECA#	064-S701
Stormwater System Name	Town of Fort Erie Stormwater Collection System
Stormwater Owner	Corporation of the Town of Fort Erie
Period Reported	January 1, 2025 to December 31, 2025

Include a summary of all monitoring data along with an interpretation of the data and an overview of the condition and operational performance of the Authorized System and any Adverse Effects on the Natural Environment.

Not applicable – waiting for Ministry to issue guidance document.

Include a summary and interpretation of environmental trends based on all monitoring information and data for the previous five (5) year.

Not applicable – waiting for Ministry to issue guidance document.

Include a summary of any operating problems encountered and corrective actions taken.

Date	Location	Issue	Corrective Actions Taken
31 Mar 25	Point Abino Pump	Pump not working	Pump removed and replaced with back-up pump

Include a summary of inspections, calibration, maintenance and repairs carried out on any major structure, equipment, apparatus, mechanism, or thing forming part of the Authorized System.

No scheduled inspections were recorded during 2025. Inspections completed in response to complaint receipt. See table below. No calibration requirements at this time. Maintenance and repairs are outlined in other areas of this report.

Include a summary of any complaints related to the Sewage Works received during the reporting period and any steps taken to address the complaints.

Date	Location	Issue	Corrective Actions Taken
19 Dec 25	Bardol Avenue	Drain clogged and water over road. Resident states if it gets too cold it will freeze and nervous it will cause an accident.	Inspection completed, no issue found.
4 Nov 25	Ridgeway Road @ Linwood Avenue	Possible sinkhole in road.	Inspection completed, watermain break was the cause.
20 Oct 25	Spears Road @ Garrison Road	Catch basin at Garrison Rd and Spears Rd, has water pooling. Possibly blocked.	Inspection completed, blockage cleared.
17 Sep 25	3018 Jewell Avenue	Catch basin lid missing.	Lid replaced.
4 Sep 25	215 South Mill Street	Large chunks of grass flipped over onto STM grate by snow plows, narrowing the grate area. Clean off to original size so that water drains properly.	Sod removed.
28 Aug 25	Ashwood Avenue	STM drains on street not draining water away properly. Flooding when it rains.	Catch basins opened and inspected no issues found.
29 Jul 25	3955 Alexandra Road	Catch basin covered with grass and weeds.	Inspection completed, catch basin cleaned off.
3 Jul 25	28 Jarvis Street in the rear	Replace broken catch basin Lid.	Replace catch basin Lid, installed new base, riser, and lid. Topped area with QPR.
3 Jul 25	3908 Erie Road	Catch basin repair.	Parge inside of catch basin around pipe, fill in sink hole.
17 Jun 25	Erie Road @ Oakwood Avenue	Loose manhole cover.	Manhole in question was for storm. New 2" lid adjustment ring added and manhole is now just below grade. Frame on manhole its self is broken and need to be replaced for a more permanent fix.

16 Jun 25	102 Champlain Drive	Sinkhole near her curbstop. Sinkhole beside catch basin. Not related to curb stop.	Set up locates. Cone left over sinkhole. Sinkhole repair work completed 21 Aug 25.
10 Jun 25	127 Shirley Road	Ensure flap gate on the Shirley Road culvert between 127 and 137 Shirley Road working properly. Ensure no maintenance holes were buried.	Staff completed an inspection of the Shirley Road box culvert and flood/flap gate. Gate appears to be in working order and was exercised by staff. Staff also located all catch basins and maintenance holes while on site to confirm that none were covered.
15 May 25	1633 Marina Drive	Storm drain in backyard is blocked by neighbour, requires cleaning out.	Private drainage matter referred to Bylaw Department.
29 Apr 25	333 Lakewood Avenue	Catch basin in front of property requires cleaning out.	Catch basin is clean at this property. Water level is below outlet.
22 Apr 25	Belvidere Street and Wellington Court	Catch basin at southeast corner of Belvidere St. and Wellington Crt. STM water not flowing into it.	Debris removed. Catch basin clear and open.
17 Mar 25	Maplewood Avenue Ave & Glenspring Road	Catch Basin is damaged needs replacement or repair.	Repair Completed. Still need to put down cold mix, Asphalt can be done later by contractor. Cones and barrel left in place for now.
5 Mar 25	60 Riceland Road	Storm sewer is clogged in this area causing flooding.	No catch basin in area. Appears to be a low spot in the yard.
25 Feb 25	3746 Crystal Beach Drive	blocked STM sewer drain.	Blockage Cleared.

Include a summary of all Alterations to the Authorized System within the reporting period that are authorized by this Approval including a list of Alterations that pose a Significant Drinking Water Threat.

No alterations pose a Significant Drinking Water Threat. 2025 alterations summarized below:

Location (Project Name)	Alteration Summary	Status
Ott Road / West Main Street	Removal of existing storm infrastructure and replace with new storm sewers. Installation of an OGS.	Construction complete.
Prospect Point Road North	Installation of storm sewers FROM: Cutler Street TO: Disher Street.	Construction complete.

Note: Construction project details included in appropriate Ministry Future Alteration Forms.

Include a summary of all spills or abnormal discharge events

No information for the reporting year.

Include a summary of actions taken, including timelines, to improve or correct performance of any aspect of the Authorized System.

No information for the reporting year.

Include a summary of the status of actions for the previous reporting year.

Not applicable – waiting for Ministry to issue guidance document.

This annual performance report of the Authorized System was prepared as required by the CLI-ECA 064-S701 Schedule E Section 5.3.2, this report will be made available by June 1st of the same reporting year, to members of the public without charge by publishing the report on the internet.

This report will also be made available on request and without charge, to members of the public who are served by the authorized system.